March 14, 2022

TO: All Lubricant Review Institute (LRI) Members

Information Letter: GL-22-01

Subject: Report Error Identified

Dear LRI Committee Members:

In January 2022, a presenting laboratory discovered an error in their L-42 reporting. The error was due to the potentiometer setting not being updated on the test reports. This error has been continuous since July 2020. The reported potentiometer settings do not impact the validity of the test. The presenting laboratory will correct all impacted reference tests in the TMC database.

Should you have any questions concerning this action, please contact me at PRI Headquarters at +1 724-772-8647 or via email at wgrubbs@p-r-i.org.

Sincerely,

Wendy L. Grubbs

Wendy L. Grubbs
QPL Development Coordinator

db/wlg